


DESCRIPTION



- P-trap, 1-1/4" with Clean-out, 17 gauge.
- Includes: (1) brass quarter bend, (1) brass clean out plug, (1) fiber clean out washer, (1) brass "J" bend with clean out, (2) rubber washers, (2) die cast nuts.
- Chrome-plated.



**P-TRAP
707-1**

